

SUPPLEMENTAL
INSTRUCTIONS

PART
NO. 510494-0000

FIXTURE TYPE _____

18/4 ST FEED
CORD MOUNTING
PI/PID3500 & PI/PID35JR00

PG. 1
OF 1

DO NOT MODIFY OR ALTER THIS PRODUCT IN ANY WAY, OR INSTALL IN ANY FASHION WHICH IS CONTRARY TO THE INSTRUCTIONS CONTAINED HEREIN.
IF YOU HAVE ANY QUESTIONS REGARDING THIS PRODUCT OR THE INSTALLATION OF IT, PLEASE CALL LITECONTROL ENGINEERING AT 781-294-0100.

GENERAL NOTE:

This installation sheet is used with aircraft cable assemblies when 18/4 ST feed cord is required.

1. To secure feed cord at fixture end of installation;
 - A) Strip off outer jacket of feed cord enough to make wiring connections.
 - B) Slide a strain relief then a 7/16" flat washer onto feed cord above knockout.
 - C) Insert feed cord thru either 5/8" or 7/8" ko's located on access cover.
 - D) Slide a 7/16" flat washer then a strain relief onto feed cord from underneath knockout.
 - E) Crimp metal strain reliefs onto cord as shown in view.

